



# **Qsan Document - Release Note**

**XN 3000/5000/8000**

**Version 3.0.3  
May 2018**

## Copyright

**Copyright@2018, Qsan Technology, Inc.** All rights reserved. No part of this document may be reproduced or transmitted without written permission from Qsan Technology, Inc.

## Trademarks

All products and trade names used in this document are trademarks or registered trademarks of Qsan Technology, Inc.

## Qsan Technology, Inc.

4F., No.103, Ruihu St.,  
Neihu Dist., Taipei City 114,  
Taiwan (R.O.C.)

Tel: +886-2-7720-2118

Fax: +886-2-7720-0295

Email: [sales@qsan.com](mailto:sales@qsan.com)

Website: [www.qsan.com](http://www.qsan.com)

## Release Information

Qsan is pleased to announce the release of QSAN XN3000/5000/7000/8000 firmware V3.0.3, the latest firmware for the following Qsan NAS products:

- Systems: XN3000/5000/7000/8000
- Firmware: 3.0.3 (May 2018)
  
- **New Features and Enhancements**
  - Set SMB default permission to 777 when create file and directory.
  - Improve the Windows Advance ACL permission setting.
  - For Translation issues, temporary remove some languages.
  - Performance tuning in huge file transmission via Thunderbolt and 10GbE interface.
  - Enhance Active Directory syncing with server behavior.
  - Adjust creation cell numbers in Quick Install page.
  - Enhance Transcode mechanism
  - Enhance event log
  - Update Windows One Drive package version
  - Enhance System configuration import/export mechanism.
  
- **Bug Fixes**
  - Fix file explorer response time too long when iSCSI LUN ran out of capacity.
  - Fix syslog failed to send certain message
  - Fix blocking IP display issue after trying certain times of logging in AFP.
  - Fix S.M.A.R.T. display issue
  - Fix S.M.A.R.T. temperature issue in certain models of disk.
  - Fix a potential issue after the system is reset to default.
  - Fix a display issue on background job task.
  - Fix File manager pin to short cut error.
  - Fix a potential issue if updating firmware unsuccessfully for sudden power outage or unexpected shutdown.

- Fix a potential configuration import/export issue.
- Fix display issue in storage page.
- Fix cloud backup randomly terminated in some situations.
- Fix snapshot rotation issue.
- Fix network gateway missing in certain situation.
- Fix antivirus schedule setting UI issue.

- **Limitations**

- None.

- **Companion Software**

	3000	5000	7000	80000
BIOS	MPT 171211	MKT 1.71 MKR 1.91	MKT 1.71 MKR 1.91	MKT 1.71 MKR 1.91
Local Expander FW	N/A	N/A	N/A	N/A
XFinder	1.0.2	1.0.2	1.0.2	1.0.2