



QSAN Document - Release Note

XN 3000/5000/7000/8000

Version 3.1.3
Mar. 2019

Copyright

Copyright@2019, QSAN Technology, Inc. All rights reserved. No part of this document may be reproduced or transmitted without written permission from QSAN Technology, Inc.

Trademarks

All products and trade names used in this document are trademarks or registered trademarks of QSAN Technology, Inc.

QSAN Technology, Inc.

4F., No.103, Ruihu St.,
Neihu Dist., Taipei City 114,
Taiwan (R.O.C.)

Tel: +886-2-7720-2118

Fax: +886-2-7720-0295

Email: sales@qsan.com

Website: www.qsan.com

Release Information

QSAN is pleased to announce the release of QSAN XN3000/5000/7000/8000 firmware V3.1.3, the latest firmware for the following QSAN NAS products:

- Systems: XN3000/5000/7000/8000
- Firmware: V3.1.3 (Mar. 2019)

New Features and Enhancements

- Support Fiber Channel topology setting
- Enhance Internet routing stability
- Enhance system stability in heavy I/O circumstance.
- Enhance disk migration error handling.
- Enhance Remote Backup stability and error handling

Bug Fixes

- Fix minor display issues on WebUI
- Fix message issues on UI message
- Fix a bug that Snapshot relocation job shows incorrect status.
- Fix a bug for unable editing existing Virtual Machine
- Fix a bug for Background job task display issue.

Limitations

- XN8016/8024/7016/7024 Wake on LAN supports only in on board 1GbE port

Companion Software

	3000	5000	7000	80000
BIOS	MPT 171211	MKT1.71 MKR1.91	MKT1.71 MKR1.91	MKT1.71 MKR1.91
Local Expander FW	N/A	N/A	N/A	N/A
XFinder	1.1.1	1.1.1	1.1.1	1.1.1